

CERTIFICATE STRUCTUREAL SAFTY/STABILITY

Certified that the Building of Sri Sathya Sai School Building Pujarli on plot No. 649, 650 & 651 measuring 6095 sqm. situated at Pujarli Shimla, submitted for approval satisfy requirements as per (Building Bye-Laws structure design) and the information given therein is factually correct to the best of our knowledge and understanding.

The structure has been visited personally and the structure of Sri Sathya Sai School building has been found safe.

1) Signature of owner with date

Name in block letter

Address

[Signature]
24/1/21
Sri Am SUNDAR

Certified that nothing has been charged for inspection above said building.

2) Signature of Architect with date

Name in block letter.

Address

[Signature]
AR. SANJIV KUMAR
AIA, MCA
Reg.No. CA-97/21668

Block - 20, flat - 8
Phase - III, New Shimla - 9.

3) Signature of the structure Engineer with date

Name in block letter

Address

Certified that nothing has been charged for inspection above this building.

[Signature]
21/04/21
MUNEESH RAT
Assistant Engineer
A. E. (D) HIMUDA, Nigam Vihar
Shimla-171002